

Notice of Violations  
Eastern Kern  
Air Pollution Control District

NOV #	Source Name	Rule/Reg # / Violation	Violation Date	NOV Date
071211	Mediacom	201 Permit Requirement for Engine 50 bhp or Greater.	06/24/11	7/12/11
082211	NASA	CCR 2458(b)(5)© Failure to properly record specific engine location for at least 14 PERP registered engines from 2010 until present	06/29/11	8/22/11
091511	Cedar Construction & Development INC	Code of Federal regulation Part 61, Subpart M, Sec. 61.145(a)(4)	08/03/11	9/15/11
092911	National Cement Co	Rule 111.III Failure to notify of a breakdown w/in 1 hour of occurrence. (Actually 5 days later)	09/06/11	9/29/11
103111 DLK	Lehigh Southwest Cement	Rule 201 - Failure to permit a limestone screening operation	11/01/10	10/31/11
120111 DLK	Lehigh Southwest Cement	Rule 422, subpart F - Visible emissions greater than 10% over a 3 minute period in one hour at the tripper belt (C3-026) on the raw mill feeding system (PTO 1147013C))	12/01/11	12/1/11
121411 GB	US Borax INC	Rule 108.1 Failure to cancel and renotify of Boiler #5 Source Test	11/10/11	11/14/11
121411a GB	Cal Aero	Rule 201 Operation of a Painting operation without a District Permit to Operate	12/09/11	12/14/11
121911 GB	Southern California Edison	Code of Federal regulation Part 61, Subpart M, Sec. 61.145(a)	11/03/11	12/19/11
122011 GB	MD Concrete Cutting & Demolition	Code of Federal regulation Part 61, Subpart M, Sec. 61.145(a)	11/03/11	12/20/11